

 AERoclubul ROMÂNIEI www.ar.ro	Service Bulletin	Doc. No.: SB-AR-05-IS-28M2
		Revision:1
		Date: 16.08.2023
EASA APDOA439	Project Reference: AR.IS-28M2.002	Page 1 of 3

Service Bulletin


No. SB-AR-05-IS-28M2

Information update for the Aircraft Flight and Maintenance Manual IS-28M2/80HP, Issue 1

List of amendments		
Revision	Date	Description
-	09.02.2022	Initial issue
1	16.08.2023	Editing and wording corrections

	Name / Position	Date	Signature
Prepared	Dan Cociu / Head designer	16.08.2023	
Approved	Florian Petcu / Airworthiness manager	16.08.2023	

F2.3-03 (01.2017)	Compliance with the local aeronautical regulation applied in the country in which the glider is operating / registered is the responsibility of the operator
----------------------	--

	Service Bulletin	Doc no.: SB-AR-05-IS-28M2
		Revision: 1
		Date: 09.02.2022
EASA AP439	Project reference: AR.IS-28M2.002	Page 2 of 3

1.1 Applicability

The Service Bulletin No. BS-AR-05-IS-28M2 applies to the motor glider type IS-28M2/80 HP (Limbach 2000).

1.2 Reason

Information update for the Aircraft Flight and Maintenance Manual IS-28M2/80HP, Issue 1

1.3 Compliance

The modification is made in accordance with the AR.IS-28M2.002 project.

1.4 Approval

The technical content of this Service Bulletin was approved under EASA's authority, reference no. 10083149/30.10.2023 and it was issued in accordance with the DOA regulations by EASA AP439.

1.5 Special tools

N/A.

1.6 Weight and balance

Not affected.

1.7 Electrical charge


Not affected.

1.8 Other affected publications:

— Aircraft Flight and Maintenance Manual IS-28M2/80HP, Issue 1 Amendment 14:

1. Cover;
2. Page I.A;
3. Page III.A, IV.A;
4. Page AM-I.A;
5. Page AM-II.B;
6. Page P.V.1.L;
7. Page 2.8.C;
8. Page 2.12.B;
9. Page 3.1.A;
10. Page 3.7.B; (for Romanian version 3.7.C)
11. Page 3.13.C;
12. Page 3.14.B;
13. Page 4.9.A, 4.10.A;
14. Page 4.13.A, 4.14.A, 4.15.A;
15. Page 4.17.C; (for Romanian version 4.17.D)
16. Page 4.19.D; (for Romanian version 4.19.C)
17. Page 4.20.A;
18. Page 4.24.B;

F2.3-03 (01.2017)	Compliance with the local aeronautical regulation applied in the country in which the glider is operating / registered is the responsibility of the operator
----------------------	--

	Service Bulletin	Doc no.: SB-AR-05-IS-28M2
		Revision: 1
		Date: 16.08.2023
EASA AP439	Project reference: AR.IS-28M2.002	Page 3 of 3

19. Page 4.43.D, 4.44.D, 4.45.D, 4.46.D;
20. Page A.3.2.A;
21. Page A.5.1.A;
22. Page 6.1 – added.

- Aircraft Flight and Maintenance Manual IS-28M2/80HP, Issue 1 Amendment 15:

1. Page AM-II.C;
2. Page P.V.1.M;
3. Page 3.7.C;
4. Page 3.14.C;
5. Page A.5.1.B;

1.9 Reporting

Any information related to this Service Bulletin can be requested to Aeroclubul României's ADOA AP439 Department at camo@ar.ro.

2. Information regarding materials

- 2.1 The list of parts that must be processed
N/A
- 2.2 New parts
N/A
- 2.3 Parts that must be changed
N/A
3. Instructions
N/A
- 3.0. Remarks
 - a) The Maintenance Program must be updated
 - b) In case of any doubt, please contact Aeroclubul României at ADOA AP439 Department (camo@ar.ro).
- 3.1 Preparations
N/A.
- 3.2 Preliminary inspections
N/A
- 3.3. Inspections
N/A.
- 3.4 Final details
The Maintenance Program must be updated.
- 3.5 Necessary actions and compliance time:

Changing the affected pages of the Aircraft Maintenance and Flight Manual changed by this Service Bulletin.

F2.3-03 (01.2017)	Compliance with the local aeronautical regulation applied in the country in which the glider is operating / registered is the responsibility of the operator
----------------------	--