	<h2>Service Bulletin</h2>	Doc.-No.: SB-IS-28M2-AR-01
		Revision: 02
		Date: 23.01.2018
EASA AP439	Project Reference: AR.IS-28M2.001	Page 1 of 5



Service Bulletin

No. SB-IS-28M2-AR-01

Modification of the technical resources of the IS-28M2 motor gliders – all variants and uniformity of the maintenance program.

Cancels and replaces the SB IS-28M2 / ER-15 and SB IS-28M2/80HP / ER-05

Log of revisions		
Revision	Revision date	Change description
01	07.10.2017	Document release
02	23.01.2018	Change corrosion control periodicity and completion paragraph 1.9 Reporting.

	Name / Function	Date	Signature
Drafted	Liviu Țurlete / Head of DOA	23.01.2018	
Approved	Florian Petcu / Airworthiness Manager	23.01.2018	

F2.3-03 (01.2017)	It is the operators responsibility to comply with the relevant aviation regulations of the country in which the product is registered and operated.
----------------------	---